

**Replacement Transformer Kits  
for 940 and 940HS**

Transformer, 506367, has been obsoleted. If this transformer needs to be replaced, the appropriate kit must be used to replace 506367. Both kits include transformer, 507293, plus each kit has the necessary wires and schematic sticker for a specific model. The kit's sticker is supplied to replace the unit's present sticker.

For 940 only, transformer, 506367, has been obsoleted and replaced by Transformer Replacement Kit, 125355. 940's, with serial numbers 3480 through 3926 inclusive, have 506367. On models after 3926, or where the kit has been previously installed, transformer 507293 replaces 506367.

For 940HS only, transformer, 506367, has been obsoleted and replaced by Transformer Replacement Kit, 125356. 940HS's, with serial number 0124 and lower serial numbers, have 506367. On models after 0124, or where the kit has been previously installed, transformer 507293 replaces 506367.