

940 and 940-220 POWERIG® Hydraulic Units Pilot Valve Design Change

The pilot valve's new design does not allow interchangeability of the *new solenoid assemblies and their components* with the older solenoid assemblies and their components. In effect, this means that earlier hydraulic units that still have the original pilot valves must have the *complete pilot valve replaced if either of the solenoid assembly's components are damaged*.

Hydraulic units equipped with the new valves are as follows:

940's, with serial number 2513 and above.

940-220's, with serial number 0598 and above.

For the redesigned valves, the following parts are available (the tube and coil are included with the solenoid assembly):

940's pilot valve, 111351 has solenoid assembly, 112649 which includes tube, 112626 and coil, 112627

940-220's pilot valve, 112119 has solenoid assembly, 112473 which includes tube, 112626 and coil, 112120

5-15-96

405



Installation Systems Division
P.O. Box 2270
Kingston, New York 12401-0250